












Manual chipping of Tiles, Machine grinding process to remove traces of adhesive & Grout and Acid wash to remove loose tiles from pool wall & floor.









Removal of overflow gratings, removal of all debris stored inside, cleaning of pipeline, acid wash of overflow drain.



Cleaning of tiles removed area, prepared it for new tiles fixing using adhesive, Tiles fixing & Pool light wiring checking & light fixing work.



New pipes for plumbing work, tanks for Overflow Balance tank, Epoxy grouting of Pool tiles



Epoxy grouting of overflow drain, Electrical control panel box, removal of damaged pipelines









Earth digging work to keep balance tanks, floor bed soling & concrete to avoid soil sliding, fixing of plumbing fittings to tank




Plumbing work, Keeping balance tanks in place, connecting tanks with plumbing lines, filling all gaps of pit with soil with proper pushing.






# Fixing of new gratings in overflow drain







Filling of pool with fresh water, testing of robotic pool cleaner with newly developed control box.



# **Beautiful View of Refurbished Swimming Pool**



PREEMIYAR POOLS PVT LTD best pool for better swimming ...

# For more information, please contact:

BENGALURU H.O.	MYSORE	HASSAN/COORG/CHIKMAGALUR
Preemiyar Pools Pvt Ltd,	Preemiyar Pools Pvt Ltd,	Preemiyar Pools Pvt Ltd,
# 593, Nesara, 2 <sup>nd</sup> Floor,	# 495, Mathrushree,	Shrungari Nilaya,
2 <sup>nd</sup> Main, Opp H.M.V School,	'G' Block,	Near MKS Lions School,
Annapoorneshwarinagar,	Ramakrishnanagar,	Fort, Konanur - 573 130,
Bengaluru - 560 091, India	Mysore - 570 006, India	Hassan Dist, India
Ph: +91- 94484 - 56552	Ph: +91- 636463 - 1155	Ph: +91-94484-60658

www.preemiyarpools.com preemiyarpools@gmail.com

